








CHIGNIK BAY, ALASKA - EROSION MONITORING SITES



Credits: Aerial Imagery provided by Alaska SDMI Statewide Ortho-Imagery Collection and ACGL

Legend

-  Camera
-  Stake
-  Coastal Profile
-  Site Location

